

Zyxel ZON Utility 2.1.6 C0

Release Note/Manual Supplement

Date: September 14, 2023

This document describes the features in the **ZON Utility** for its 2.1.6 C0 release.

Release file list:

File Name	Remark
ZON 2.1.6 C0 Release Note.doc	This file.
Zyxel ZON Utility.exe	Installation file include “ZON utility and ZAC” SHA256 checksum is “6e2a07ca6d0e90250ae738990ae4670893abec0e6665226faa42801 b3639c29a”
en-US-utf8.cfg	The string resource file. SHA256 checksum is “0047b318962486dc6c186331716bbd017a9089a2fff46aca2cca1853 2cccc241”

Supported Platforms

Operation System Support

- Windows 7 32bit / 64bit
- Windows 8 32bit / 64bit
- Windows 8.1 32bit / 64bit
- Windows 10 32bit / 64bit
- Windows 11

Hardware Requirements

- Core i3 processor or above
- 2GB RAM or above

- 100MB free hard disk or above
- WXGA (Wide XGA 1280x800) and above display

Version

Software Version: 2.1.6 C0

New Feature and Enhancements

1. The latest supported models URL has been updated. It will open in your default web browser.
2. The default filename for exporting is changed to "ZON.csv".

Bug fix

1. Remove unusable blank network adapters in the network adapter list.

Known Issue

1. [ZON] ZON utility V2.1.3 and lower versions are not compatible with GS1900 V2.50. Functions requiring password authentication will fail to authenticate due to previous ZON versions does not support GS1900 V2.50 password authentication algorithms.

Features:

- Quick search
- Set up IP configuration
- Renew devices' IP address (for DHCP mode only)
- Reboot devices
- Reset configuration to default
- Turn on devices' locator LED
- Change devices' web GUI
- Launch devices' web GUI

- Upgrade same model devices' firmware
- Launch ZAC with discovered AP(s)
- Import language files

Limitation of Settings:

1. Length of system name: 64
2. Length of location: 32
3. Length of new administrator password: 32
4. IPv4 address Mandatory
5. Subnet mask Mandatory
6. Administrator password Mandatory
7. Discovered number of devices 250 devices
8. [Firmware Upgrade] ZON only support one IP address on NIC card to do firmware upgrade.
9. [Firmware Upgrade] Firewall should disable when firmware upgrade.
10. [Firmware Upgrade] If device firmware upgraded fail, ZON doesn't have return error mechanism.

Support Models

<https://www.zyxel.com/global/en/form/zon-utility-download>